

ITEM 6  
MANAGER'S REPORT NO. 75  
COUNCIL MEETING 1979 11 05

RE: PETITION FROM RESIDENTS ON HIGHFIELD DRIVE AND NORTH SEA AVENUE  
WHICH APPEARED ON THE AGENDA FOR THE 1979 OCTOBER 29 MEETING OF  
COUNCIL (ITEM 6g)  
REQUEST FOR INSTALLATION OF A STREET LAMP

Appearing on last week's agenda was a petition requesting the installation of a street lamp on a power pole on Highfield Drive. Following is a report from the Municipal Engineer on this matter.

RECOMMENDATION:

1. THAT the recommendations of the Municipal Engineer be adopted.

\* \* \* \* \*

TO: MUNICIPAL MANAGER 79 10 31  
FROM: MUNICIPAL ENGINEER  
SUBJECT: PETITION FROM THE RESIDENTS OF HIGHFIELD DRIVE AND  
NORTH SEA AVENUE

RECOMMENDATIONS:

1. THAT Council approve the installation of an interim light on the hydro pole between 5823 and 5827 Highfield Drive.
2. THAT a copy of this report be sent to the petitioners.

REPORT

We have investigated the request outlined in the above petition for installation of an additional interim light on the hydro pole between 5823 and 5827 Highfield Drive.

We are planning the installation of ornamental street lighting in the Capital Hill area under the 1980 Local Improvement Program. Ornamental street lighting is planned for Warwick Avenue between Dundas Street and Highfield Drive but Highfield Drive is not included in the program.

The existing interim light spacing is adequate under Council's policy on the spacing of lights, but we found that the grade and curve on Highfield Drive severely limits the effectiveness of the existing lights. For safety reasons and because Highfield Drive is not included in the 1980 L.I.P., we are recommending the installation of an additional light on the pole indicated in the petition.

The locations of the existing lights and the proposed light have been indicated on the attached sketch.

  
MUNICIPAL ENGINEER

RB/ch  
Att.  
c.c. ( ) R.C.M.P.  
( ) Traffic Supervisor

