

RE: PROPOSED DEMOLITION

LOTS 3 AND 5, BLOCK 4 AND PARCEL "A", (R.P. 3131)  
OF LOT 4, BLOCK 4 ALL OF D.L. 160, GROUP 1, PLAN 992  
6825 TWENTIETH AVENUE

ITEM 3  
MANAGER'S REPORT NO. 3  
COUNCIL MEETING 1983 01 10

MUNICIPAL MANAGER'S RECOMMENDATION:

1. THAT the recommendation of the Municipal Solicitor be adopted.

\* \* \* \* \*

January 4, 1983

TO: MUNICIPAL MANAGER  
FROM: SOLICITOR  
RE: 6825 - 20th Avenue  
Lots 3 and 5, Block 4 and Parcel "A" (R.P. 3131)  
of Lot 4, Block 4 all of District Lot 160, Group 1,  
Plan 992

RECOMMENDATION:

THAT the tenants be given the required four (4) months' notice to vacate and the residence and outbuildings be demolished immediately after the residence is vacated.

R E P O R T

The subject property was purchased by The Corporation of the District of Burnaby in May 1977 for the sum of \$120,000 (Manager's Report No. 36, Council Meeting May 9, 1977). The property has a total area of approximately 77,620 sq. ft. of which 37,460 sq. ft. is readily useable, with the remaining 40,160 sq. ft. being ravine property.

There is situated on the subject Lot 5 a small residence consisting of two bedrooms, a living room, kitchen and bathroom with a total area of approximately 800 sq. ft. but as this residence was in poor condition at the time of purchase, the price paid reflected land value only. At the time of purchase the residence was rented to a Mr. and Mrs. Hutton (former owners) and it was agreed at that time, although the residence was in a rather bad state of repair, Mr. and Mrs. Hutton could stay on as tenants for \$150 per month (the present rental is \$182 per month). They were advised at that time that the Corporation did not intend to spend any money on this residence, other than the normal maintenance costs on the furnace and hot water tank and that should the building ever reach a condition where our Building Department recommended demolition, a report would be presented to Council for their approval to demolish.

MUNICIPAL MANAGER

(2)


ITEM 3  
MANAGER'S REPORT NO. 3  
COUNCIL MEETING 1983 01 10

107

In all fairness to the tenants (Mr. and Mrs. Hutton) they have not caused us to spend any money on this residence and have taken care of any problems that have arisen. However, over the last year we have had a growing uneasiness over the condition of this residence and the safety of the tenants and requested the Building Department to conduct a full survey of the residence and submit their report to this Department. We have now received this report (copy attached) which we feel is self-explanatory and which would seem to justify our concern that this residence is substandard rental accommodation and should be demolished.

It is estimated by our Maintenance Division of the Engineering Department that the cost of rectifying all the problems on the Building Department report would be approximately \$18,000. This figure would not represent the probable added costs of a new furnace or hot water tank as well as other cosmetic expenses to bring this residence up to a good standard rental accommodation.

We concur with the report and herewith request Council approval to give the tenants four (4) months' notice and the house demolished as soon as we have vacant possession. Pictures of the property will be available for viewing at the 1983 January 10 Council Meeting.




W. L. Stirling  
MUNICIPAL SOLICITOR

RPAustin/gmc

cc: Director Planning and Building Inspection  
Treasurer  
Municipal Clerk  
Chief Building Inspector

Attach.



THE CORPORATION  
OF THE DISTRICT OF  
**BURNABY**

4949 Canada Way, Burnaby, B.C. V5G 1M2

Building Department

ITEM 3  
MANAGER'S REPORT NO. 3  
COUNCIL MEETING 1983 01 10

Telephone (604)

294-7137

1982 October 29

Mr. W.L. Stirling  
MUNICIPAL SOLICITOR

Subject: 6825 - 20th Avenue, Burnaby

Relative to a request from Fred Forder, Maintenance Division of the Engineering Department, a survey of the above-noted property was undertaken by this department and the comments of the various inspection divisions are listed hereunder for your information:

Building:

1. The floor joists and sub-flooring appears to be badly decayed.
2. The bedroom, kitchen and living room floors are sloping, due to poor supports under the floor joists.
3. The roof rafters appear to be decayed.
4. The roofing material needs to be replaced.
5. Repairs are required to the exterior shingle cladding.
6. Repairs are required to the front porch supports and steps.
7. The duct work connecting to the oil-fired furnace has deteriorated and is falling apart, and needs to be replaced.

Plumbing:

The entire plumbing system is beyond repair and needs to be replaced.

Electrical:

1. There is no provision for locking or for security of the existing 60 amp. main switch. The switch would be satisfactory if it were relocated inside the building or provided with a lock.

Mr. W.L. Stirling  
MUNICIPAL SOLICITOR

- 2 -

ITEM	3
MANAGER'S REPORT NO.	3
COUNCIL MEETING	1983 01 10

Electrical cont'd

109

2. The 8-position fuse panel is inadequate and should be replaced with a minimum 16-position breaker panel with an integral main breaker. Alternatively, the existing 60 amp. main switch could be reused with a new 16-position breaker panel.

3. Additional circuits are required:

- (a) kitchen bench - 2 (split)
- (b) fridge - 1
- (c) dryer - 2
- (d) washing machine - 1
- (e) furnace - 1

4. Additional outlets are required in the living room, bedroom (ground fault circuit interrupters), and the exterior (ground fault circuit interrupters).

In summary, the building is considered to be in poor condition generally and appears to be economically beyond repair. Demolition is recommended.

JS:lm

*Frank R. Mehling*

Frank R. Mehling, P.Eng.  
DEPUTY CHIEF BUILDING INSPECTOR

c.c. Fred Forder, Maintenance  
Division, Engineering Dept.