

ITEM 13
MANAGER'S REPORT NO. 77
COUNCIL MEETING Dec. 1/75

Re: MUD ON PATTERSON AVENUE BETWEEN IMPERIAL STREET AND RAILWAY TRACKS

On October 14, 1975, Council inquired about the presence of mud on Patterson Avenue between Imperial Street and the tracks which was believed to have resulted from construction activity in the area. Following is a report from the Municipal Engineer on this matter.

This is for the information of Council.

* * * * *

TO: MUNICIPAL MANAGER 28 NOVEMBER, 1975
FROM: MUNICIPAL ENGINEER
RE: MUD ON PATTERSON AVENUE BETWEEN IMPERIAL STREET
AND RAILWAY TRACKS

At the October 14, 1975 Council meeting an enquiry was made regarding the above-captioned subject.

Since being notified by the Municipal Clerk of that enquiry, the Engineering Department has monitored the subject street for mud emanating from the construction sites along the street. During that period we have had the occasion to make two requests to construction firms for cleaning of the streets. Both requests were responded to promptly and cleanup was effected.

It has been the Engineering Department's experience that when these matters are brought to the attention of the construction firms we receive good cooperation.

At present the Engineering Department does not have sufficient staff to cover the comprehensive developments and commercial developments as often as we would like. Also at present we do not inspect residential construction.

It is the Engineering Department's intention to improve the situation with the addition of one additional Claims & Bylaw Inspector. This item has been included in the Engineering Department 1976 Provisional Budget.

This is for the information of Council.

VMT:wlh


MUNICIPAL ENGINEER