ITEM 10
MANAGER'S REPORT NO. 31
COUNCIL MEETING Apr. 25/77

Re: LETTER FROM MR. WILLIAM A. CAMPBELL WHICH APPEARED ON THE AGENDA FOR THE APRIL 18, 1977 MEETING OF COUNCIL (Item 5c) SIDEWALK ON SUSSEX AVENUE BETWEEN BERESFORD AND KINGSWAY

Appearing on last week's agenda was a letter from Mr. William A. Campbell regarding the condition of a sidewalk on Sussex Avenue. Following is a report from the Municipal Engineer on this matter.

The Manager has instructed the Engineer to replace the existing sidewalk with an asphalt walkway with funds from the Engineering Maintenance Budget.

RECOMMENDATION:

1. THAT a copy of this report be sent to Mr. W. A. Campbell.

* * * * * * *

18 April, 1977.

TO: MUNICIPAL MANAGER

FROM: MUNICIPAL ENGINEER

SUBJECT: SUSSEX AVENUE SIDEWALK BETWEEN BERESFORD AND KINGSWAY.


On the Council Agenda for April 18, 1977 under 'Correspondence and Petitions' Council received a letter from William A. Campbell of Suite #101 6585 Sussex Avenue, concerning the condition of the subject sidewalk.

Mr. Campbell is quite correct in his assessment of the condition of the sidewalk. The sidewalk was installed prior to the existence of the present commercial operations and is therefore not of sufficient design to accommodate the present use.

It has taken several years of heavy use to bring the sidewalk to its present state of disrepair. The Engineering Department has been reluctant to replace the sidewalk before now because of the exceptionally high cost of replacement with reinforced concrete. On the other hand, a Local Improvement project is not tenable because of road allowance deficiencies; The present road allowance is only 33 feet wide.

134

cont'd



296 MUNICIPAL ENGINEER

.

VMT:cj

Тўс.

1.1

1

(Manager)