

ITEM

MANAGER'S REPORT NO.

COUNCIL MEETING

5

6

1984 01 23

RE: LETTER FROM MRS. E.M. LYNN WHICH APPEARED ON THE AGENDA FOR THE
1984 JANUARY 16 MEETING OF COUNCIL (ITEM 5e)
LIGHTING AT BERESFORD AND OLIVE AVENUE

MUNICIPAL MANAGER'S RECOMMENDATION:

1. THAT the recommendation of the Director Engineering be adopted.

* * * * *

TO: MUNICIPAL MANAGER 84 01 18
FROM: DIRECTOR ENGINEERING
SUBJECT: LETTER FROM MRS. E.M. LYNN, 5992 OLIVE AVENUE

RECOMMENDATION:

1. THAT Mrs. E.M. Lynn, 5992 Olive Avenue, Burnaby, B.C.,
V5H 2P5, receive a copy of this report.

REPORT:


As a result of Mrs. Lynn's letter, we checked the poles at the intersection of Beresford Street and Olive Avenue for the possibility of having B.C. Hydro install a lease light. We found that the new B.C. Telephone Company pole on the northeast corner of the intersection may be suitable for a light. We will contact B.C. Hydro as soon as their current labour dispute has been settled and ask that they consider this installation.

The road damage on the northeast corner of Beresford Street and Olive Avenue, as mentioned in Mrs. Lynn's letter, has been investigated and appears to have been caused by the heavy construction vehicles being used on the A.L.R.T. construction. This matter has been passed on to our works crews who will institute repairs, the costs of which will be passed on to the B.C. Transit.

Mrs. Lynn was contacted and advised of the actions being taken on her submission.

RB:HB:sp

cc: () Traffic Supervisor


DIRECTOR ENGINEERING