

ITEM 4
MANAGER'S REPORT NO. 51
COUNCIL MEETING 87/08/24

RE: WORK ORDERS:

No. 60-30-060 - Design and Construction of Sanitary Sewer Facilities in Big Bend Area
No. 60-14-106 - Boundary Road at Marine Way - Municipal Share of Signal Revision

ACTING MUNICIPAL MANAGER'S RECOMMENDATION:

1. THAT the recommendation of the Director Engineering be adopted.

* * * * *

TO: MUNICIPAL MANAGER 1987 AUGUST 19
FROM: DIRECTOR ENGINEERING

SUBJECT: WORK ORDER NO.'S 60-30-060 - DESIGN AND CONSTRUCTION OF
SANITARY SEWER FACILITIES IN THE BIG BEND AREA (WIGGINS
PUMP STATION AREA), AND 60-14-106 - BOUNDARY ROAD AT
MARINE WAY - MUNICIPAL SHARE OF SIGNAL REVISION

RECOMMENDATIONS:

THAT Work Order No.'s 60-30-060 - Design and Construction of
Sanitary Sewer Facilities in the Big Bend Area (Wiggins
Pump Station Area), and 60-14-106 - Boundary Road at
Marine Way - Municipal Share of Signal Revision, be
approved.

60 30 060 Design and Construction of Sanitary
Sewer Facilities in Big Bend Area (Wiggins
Pump Station Area)
CHARGE: 1987 - 1991 Capital Budget \$ 374,000
Code 30 - Sanitary Sewers

ADDITIONAL INFORMATION: The Municipality
is committed to providing sanitary sewer
facilities in the Wiggins and Marshland
area of Big Bend. Additionally, the
Burnaby Refuse Incineration Plant, which
is situated in the Big Bend, is now
scheduled to begin testing operations in
late fall 1987, and the time is now
appropriate to provide a fully
functioning sanitary sewer system. Funds
are available within the 1987 Sanitary
Sewer Budget. The funds will be utilized
to pay for design and supervision of
construction as well as for the
construction itself.

ITEM 4
MANAGER'S REPORT NO. 51
COUNCIL MEETING 87/08/24

-2-

105

60 14 106 Boundary Road at Marine Way - Municipal
Share of Signal Revision
CHARGE: 1987 Capital Budget \$ 3,250
Code 60-14 - Traffic Management

ADDITIONAL INFORMATION: Municipal share of signal revision at Marine Way and Boundary Road. The work involves installation of a protected/prohibited left turn phase for the eastbound Marine Way to northbound Boundary Road movement to resolve a heavy accident problem. Funds are provided in the 1987 Capital Budget.


DIRECTOR ENGINEERING

AAS/HB:m1
cc: Director Finance