

Re: LETTER FROM HARJINDER SINGH POWER, 3722 S.E. MARINE DRIVE, BURNABY, B.C.,  
V5J 3E2 REGARDING SPEEDING 3700 BLOCK MARINE DRIVE

ACTING MUNICIPAL MANAGER'S RECOMMENDATION:

1. THAT the recommendation of the Director Engineering be adopted.

\* \* \* \* \*

**TO: MUNICIPAL MANAGER** 1986 DECEMBER 29

**FROM: DIRECTOR ENGINEERING**

**SUBJECT: SPEEDING 3700 BLOCK MARINE DRIVE**

RECOMMENDATION:

THAT Harjinder Singh Powar, 3722 S.E. Marine Drive, Burnaby B.C.  
V5J-3E2 be sent a copy of this report.


R E P O R T

Harjinder Singh Powar wrote to Council by letter dated 1986  
December 10 concerning speeding on Marine Drive.

The problem of speeding as alleged in the submission refers to  
the eastbound movement on Marine Drive. Motorists going  
eastbound on the Vancouver side of Boundary Road become  
accustomed to travelling on a straight section of road with  
little parking and only a few driveways and, as a result, do tend  
to speed. When entering Burnaby they cross Boundary Road on a  
bridge which turns into a down grade to Joffre Avenue. The  
vertical curve over the bridge does cause some sight problems  
which would be of concern to anyone entering or leaving  
properties on Marine Drive.

In order to inform eastbound Marine Drive motorists of the  
existence of possible conflicts, an advance warning sign of  
"Restricted Vision" with a 30 kph cautionary speed limit is being  
installed.

HB:dp

  
DIRECTOR ENGINEERING