

ITEM 8
MANAGER'S REPORT NO. 3
COUNCIL MEETING 88/01/11

RE: WORK ORDER

NO. 60-32-069 - VARIOUS LOCATIONS INSTALLATION OF CATCH BASINS

MUNICIPAL MANAGER'S RECOMMENDATION:

1. THAT the recommendation of the Director Engineering be adopted.

* * * * *

TO: MUNICIPAL MANAGER 1988 JANUARY 05
FROM: DIRECTOR ENGINEERING

SUBJECT: WORK ORDER NO. 60-32-069 - VARIOUS LOCATIONS -
INSTALLATION OF SIDE INLET CATCH BASINS

RECOMMENDATIONS:


THAT Work Order No. 60-32-069 - Various Locations -
Installation of Side Inlet Catch Basins, be approved.

60 32 069 Various Locations - Installation
of Side Inlet Catch Basins
CHARGE: 1987 Capital Budget \$20,000
Code 32 - Storm Sewers

ADDITIONAL INFORMATION: The 1987
Capital Budget contains provision
for the installation of side inlet
catch basins. The catch basins are
installed at low points in streets
to provide added protection against
flooding.

AAS:ml

cc: Director Finance


J. W. C. STEBBINS
DIRECTOR ENGINEERING