

ITEM 20
MANAGER'S REPORT NO. 55
COUNCIL MEETING 88/09/06

RE: WORK ORDERS:

60-32-079 - STORM SEWER, MCDONALD AVENUE, STILL CREEK SOUTH
60-14-116 - TRAFFIC SIGNAL, CURTIS STREET AND DUTHIE AVENUE

MUNICIPAL MANAGER'S RECOMMENDATION:

1. THAT the recommendation of the Director Engineering be adopted.

* * * * *

TO: MUNICIPAL MANAGER 1988 AUGUST 29

FROM: DIRECTOR ENGINEERING

SUBJECT: WORK ORDERS NO. 60-32-079 - MCDONALD AVE., STILL
CREEK SOUTH, STORM SEWER; NO. 60-14-116 -
INSTALLATION OF A FULLY ACTUATED TRAFFIC SIGNAL,
CURTIS STREET AND DUTHIE AVENUE

RECOMMENDATION:

THAT Work Orders No. 60-32-079, McDonald Avenue - Still Creek South, Storm Sewer; No. 60-14-116, Installation of a fully actuated traffic signal, Curtis Street and Duthie Avenue, be approved.

60-32-079

Provision of a storm sewer on McDonald Avenue, Still Creek South.

CHARGE:

1988 Capital Budget \$70,000
Code 32 - Storm Extensions

ADDITIONAL INFORMATION: This work order pertains to the provision of storm sewer on McDonald Avenue, Still Creek South. Funds are provided in the 1988 Capital Budget under Storm Extensions, Code 32.

60-14-116

Installation of fully actuated traffic signal, Curtis Street and Duthie Avenue.

CHARGE:

1988 Capital Budget \$43,000
Code 14 - Traffic Management

ADDITIONAL INFORMATION: Council, at its regular meeting of 1988 July 25, authorized the installation of a traffic control device at the subject location. Funds are provided in the 1988 Capital Budget under Traffic Management, Code 14.

AAS:ka

cc: Director Finance


DIRECTOR ENGINEERING