

ITEM	12
MANAGER'S REPORT NO.	38
COUNCIL MEETING	89/05/23

RE: WORK ORDERS:
 60-32-082 - Various Locations - Catch Basins
60-60-024 - Office Renovations - Justice Building

MUNICIPAL MANAGER'S RECOMMENDATION:

1. THAT the recommendation of the Acting Director Engineering be adopted.

* * * * *

TO: MUNICIPAL MANAGER 1989 MAY 16

FROM: ACTING DIRECTOR ENGINEERING

SUBJECT: Work Orders:

60-32-082 - Various Locations - Installation of side inlet catch basins.

60-60-024 - Office Renovations - Justice Building.

PURPOSE: To obtain approval of Work Order Nos. 60-32-082 and 60-60-024.

RECOMMENDATION:

1. THAT Work Order Nos. 60-32-082 and 60-60-024, as more specifically referred to in this report, be approved.

REPORT

60-32-082 Various Locations - Installation of side inlet catch basins.

Charge: 1989 Capital Budget
 Code 32: Storm Sewers \$20,000

Additional Information: The 1989 Capital Budget contains provision for the installation of side inlet catch basins. The catch basins are installed at low points in streets to provide added protection against flooding. Funds are provided in the 1989 Capital Budget under Storm Extensions, Code 32.

ITEM	12
MANAGER'S REPORT NO.	38
COUNCIL MEETING	89/05/23

60-60-024 Office Renovations - Justice Building.

173

Charge: 1989 Capital Budget
Code 60: Justice Building \$64,496

Additional Information: The 1988-1992 Capital Budget contained provision for office renovation/alterations as recommended by Unecon Consultants in their review of space requirements of the R.C.M.P. detachment. The renovations were not undertaken in 1988 and funding was therefore brought forward to 1989. The additional office space is now required and renovations would commence at the earliest opportunity.

Funds are provided in the 1989-1993 Capital Budget under Justice Building, Code 60.


ACTING DIRECTOR ENGINEERING

AAS:je

cc: Director Finance