

Re: Barricade at Casewell Street and North Road
(Item 1, Report No. 9, February 10, 1975)

On February 10, 1975, Council tabled a report on the location of the barricade at Casewell Street and North Road. The additional information requested by Council at that time is contained in the following report from the Municipal Engineer.

RECOMMENDATIONS:

1. THAT no alterations be made in the present barricade now in place on Casewell Street at North Road; and
2. THAT the owner of the apartment development at 3055 North Road, who has requested that consideration be given to the relocation of the barricade, be advised accordingly.

* * * * *

TO: MUNICIPAL MANAGER
FROM: MUNICIPAL ENGINEER
RE: 3055 NORTH ROAD

FEBRUARY 13, 1975

Reference our previous report dated February 3, 1975.

At its meeting of February 10, 1975, Council requested that further input be provided on the subject of relocating the Casewell Street barricade by obtaining the views of the three single family homes that would be affected by such action.

We have made contact with all three property owners and obtained the following opinions:

9985 David Drive - In favour of relocating barricade on Casewell Street and installing some control in lane.

9988 Casewell Street - Not in favour of any barricades but if they must be, would prefer them to remain in their present position.

2973 North Road - Did not care one way or the other.

In making a decision on the request of 3055 North Road to relocate the Casewell Street barricade, we would again suggest that serious thought be given to:

1. The precedent being set if barricades are adjusted simply upon request.
2. If the lane is left open, with or without speed bumps, it will experience a sharp increase in volume because it will be the most convenient access to North Road for area residents if not for commuters.

RECOMMENDATION:

THAT no alterations be made in the present barricade now in place on Casewell Street at North Road.

HB:wlh
cc: () Traffic Supervisor


MUNICIPAL ENGINEER