

ITEM	22
MANAGER'S REPORT NO.	27
COUNCIL MEETING	Apr. 12/77

Re: LANE BETWEEN FULWELL AND HARDWICK STREET
 EAST FROM GODWIN AVENUE TO THE EASTERN PROPERTY LINE,
 LOT 15, BLOCK 5, D.L. 76, PLAN 1885

Following is a cost report from the Municipal Treasurer on the paving of the subject lane.

RECOMMENDATIONS:

1. THAT the cost report be received; and
2. THAT a construction by-law be brought forward.

* * * * *

6 April 1977

File: 152-9

TO: MUNICIPAL MANAGER

FROM: MUNICIPAL TREASURER

RE: LANE BETWEEN FULWELL STREET AND HARDWICK STREET
 EAST FROM GODWIN AVENUE TO THE EASTERN PROPERTY LINE,
 LOT 15, BLOCK 5, D.L. 76, PLAN 1885

On 4 April 1977, Council received from the Municipal Clerk a Certificate of Sufficiency covering the paving of the subject lane as a local improvement by the petition method.

Following is a cost report which is required by Section 601 of the Municipal Act:

Length of work	380.00'
Estimated cost of work	\$ 9,500.00
Actual frontage	725.55'
Taxable frontage	708.88'
Owners' share of the cost of the work	\$ 1,501.41
Estimated lifetime of the work in years	10
Frontage tax levy	5 instalments of \$.57 per taxable front foot

RECOMMENDATIONS

1. THAT the cost report be received; and
2. THAT a construction by-law be brought forward.

Best Manager
 MUNICIPAL TREASURER

EM:gw

cc: Municipal Solicitor
 Municipal Clerk
 Municipal Engineer
 Director of Planning
 Area Assessor