Re: LETTER FROM MR. AND MRS. G. R. MACKIE WHICH APPEARED ON THE AGENDA FOR THE APRIL 12, 1977 MEETING OF COUNCIL(ITEM 4F) TRAFFIC CONDITIONS ON MEADEDALE DRIVE

Appearing on last week's agenda was a letter and petition from Mr. and Mrs. G. R. Mackie requesting the closure of Howard Street at Meadesdale Drive and "some form of traffic control and enforcement." Following is a report from the Municipal Engineer on this matter.

RECOMMENDATION:

1. THAT a copy of this report be sent to Mr. and Mrs. G. R. Mackie.

\* \* \* \* \*

15 April, 1977.

29 18/77

Apr

**COUNCIL MEETING** 

MANAGER'S REPORT NO.

ITEM

2,87,	1.5		1 (SA		See.	28.		. <i>14</i>				÷ - 6	÷4.				4.15	14	663	6 N		1.1	¥γ.	14.2	10-0	W2. 1		1.17	1221	
8y.*	÷.,	m	O	•		217	223	1.1	i, in		M	ŤΤ	٦T	T	0	T1	D	ר ה	12	÷ 1	17	17	17	10	τ.	22	•	144	£.),	÷.,
1.50	Ci,	1	U,	ē i	ЪđЫ	1.50	31 m	4.0	5 A.)	650	7.1	U.	7.4	1			54	·	4	2 🛓	ч.	71	N.C.	24			64	23	11	14.2
	743	$E^{-1}$	19.0	- 97	çe.	11.12	100	÷.,	0.00	a Órs	15-12	$M_{\rm eff}^{\rm eff}$		175	2.0	11.1	377		1.2	25.1	14	12	- N. J. J	20.1	S.a.	ыĞ	8. S. S.		Y.,	
		15	257	1.1	5.	100	1011	47			1.85	× .	1.5	17 D	2.4	372	ιù,	111	90	110		1.7	20	ч., с., с., с., с., с., с., с., с., с., с		3.4	1999	161		
КŢ		(A)	6.7	-9	943	3.5		224	2,163	10.	3.95	1.1	1.1	(Charl	25	-C.Y.	191	23.5	și tul	73	10	49	. W	с÷.;	919	ių.	See.	St to	0.97	
	87.	-	-	$\sim$		<u>`</u> ^,		1,41	te.		20			-	-	-	-		÷	27		-					-	1.1	20	
. Ť.	Ξ.	r.	R	U	м	2.3	1.5	17.3	1.1.1	6.6	м	U	N	Т	C.		21	Α.	1			чt	Ξ.	LΓ	11	11	ER	<u></u>		
22	27	212			122	7.2	7.633		75.5	-25	G (7				1.1.1	1.1	a da		. 11	19.10				02.5	25.74		- T.	2.03		1924
1.1				1.11			ШP, e	157													6 P		1.11					la esta	1.1	
÷.,		19.19	her (2)	÷ģe,	e i pie	18.	177	. 1	$i \neq j$	Ψ. 3,	·	1150	200	92	90.)		6,7		inny	90C	СĽ.,	1.0	2.466	. " · ·	92.2	157	2.7.7	3 S. I	10	-22
GN	12				<u>.</u>	21.	240		1.33	Q4 V			23	<u>Ľ</u> .	<u> </u>	22.6	1	1911	- 14	ć	11		1.12	241	1.55	31	G. 3	٥i '	10	К÷.
.77	93.	S	II	А.	T	Ε.	7	Γ.	8	اليعدي	м	F	Δ	n	E.	n	Δ1	г.1	÷	ा	זר	2.	г٦	71	1.1	25.,	2.32	4.42	Q.,	14-
7.42	10	-	ч.	-	<b>.</b>	-	-	•	• A.N.	ang,	•	-	-	-		~			- 0	-, <b>*</b>							683	8.0		
57	$\mathcal{D}$	12	1.14	1,6e	ೆಂ	1.1	99. E. B	1651	96° î	40%	12.1	χ.,		15-4	6 P	利がも	1.10	2.0	11	619	4.30	-17	: 3 <del>b</del>	96 I	98° '	Ъ.С	¥2.13	12.25	-732	

Reference: The submission from Mr. & Mrs. G. R. Mackie of 5342 Meadedale Drive and attached petition for the barricading of Howard Street at Meadedale plus some form of traffic control and enforcement.

One of the signatures on the petition, a Mr. Robert Bird of 5323 Meadedale has also suggested speed bumps be installed in the lane parallel to Meadedale.

In regard to this latter request we have written to Mr. Bird and advised him that under a Council policy we will install speed bumps in the lane at the cost of those requesting them. Attached with this letter was a plan of the bump locations and an estimate of the total cost to the applicant.

In regard to the request for the barricading of Howard Street, we would advise that further information must be gathered before a report can be submitted on this request. This report will be ready for the Council meeting of April 25, 1977.

Enforcement of existing traffic regulations will be undertaken by the R. C. M. P.

The above is for the information of Council.

MUNICIPAL ENGINEER 0

HB:cj Attach. cc: ( )

> ( (

) Traffic Supervisor ) R. C. M. P. ) Planner

145