

ITEM	3
MANAGER'S REPORT NO.	67
COUNCIL MEETING	1979 10 09

RE: ENGINEER'S SPECIAL ESTIMATES

Following for the consideration of Council is the Municipal Engineer's report covering Special Estimates of Work in the total amount of \$30,000.

RECOMMENDATION:

1. THAT the estimates as submitted by the Municipal Engineer be approved.

TO: MUNICIPAL MANAGER 79 10 03
 FROM: MUNICIPAL ENGINEER
 SUBJECT: SPECIAL ESTIMATES

I wish to submit the following special estimates for your consideration.

W.O. #

- | | | |
|--------|---|----------|
| 62-001 | Cameron Street at North Road.
Replace signal controller.
CHARGE: Code 15-08
ADDITIONAL INFORMATION: Replacement signal controller for Cameron Street and North Road. This existing actuated controller is old and obsolete and is becoming very expensive to maintain. This controller is cost shareable with the Ministry of Highways and the District of Coquitlam. Money is provided in the 1979 Capital Budget. | \$ 6,000 |
| 62-099 | Austin Avenue at North Road.
Replace signal controller.
CHARGE: Code 15-08
ADDITIONAL INFORMATION: Replace signal controller for Austin Avenue and North Road. This existing actuated controller is old and obsolete and is becoming very expensive to maintain. The new controller is also required to provide separate left turn phasing on North Road. This controller is cost shareable with the Ministry of Highways and the District of Coquitlam. Money is provided in the 1979 Capital Budget. | \$14,000 |
| 62-002 | Broadway at North Road.
Install new traffic control device.
CHARGE: Code 15-08
ADDITIONAL INFORMATION: New signal installation at the intersection of Broadway and North Road. This signal is cost shareable with the District of Coquitlam. Money is provided in the 1979 Capital Budget. | \$10,000 |
| | | \$30,000 |


MUNICIPAL ENGINEER