

ITEM 3
MANAGER'S REPORT NO. 52
COUNCIL MEETING 1983 08 22

RE: WORK ORDER NO. 60-14-070

ACTING MUNICIPAL MANAGER'S RECOMMENDATION:

1. THAT the recommendation of the Director Engineering be adopted.

* * * * *

TO: MUNICIPAL MANAGER 83 08 17
FROM: DIRECTOR ENGINEERING
SUBJECT: WORK ORDER

RECOMMENDATION:

1. THAT Work Order No. 60-14-070 be approved.

W.O. #

60-14-070 Replace fire signal at Kingsway and
Marlborough Avenue.
CHARGE: 1983 Capital Budget, Code 14. \$3,500.
ADDITIONAL INFORMATION: This Work
Order is required to replace existing
damaged and obsolete fire signal with
new standard sign and two flashing
lights actuated from #3 Fire Hall.
Funds are provided in the 1983 Capital
Budget, Traffic Management.

\$3,500.

/sp


DIRECTOR ENGINEERING