

ITEM	1
MANAGER'S REPORT NO.	9
COUNCIL MEETING	1983 02 07

RE: WORK ORDERS
NUMBERS 60-70-098 AND 60-14-066

ACTING MUNICIPAL MANAGERS RECOMMENDATION:

1. THAT the recommendation of the Director Engineering be adopted.

* * * * *

TO: MUNICIPAL MANAGER 83 02 02

FROM: DIRECTOR ENGINEERING

SUBJECT: WORK ORDERS


RECOMMENDATION:

1. THAT Work Order Nos. 60-70-098 and 60-14-066 be approved.

W.O. #

60-70-098	Construct vehicle crossings to Municipal lots for sale: Lots 307 - 311 Birkdale Place Lots 303 - 306 Glen Abbey Drive. CHARGE: Code 70 <u>ADDITIONAL INFORMATION:</u> It is Corporation policy to construct vehicle crossings at no charge to lots sold by the Corporation to fulfill our obligation to sell fully serviced lots. The crossings will be constructed when building plans have been submitted and building permits issued. Manager's Report No. 5, Item 3, 1983 01 24, advises that the lots described herein will be offered for sale as well as unsold lots described in our work order 60-70-092 received in Council 1983 01 04.	\$ 4,050
-----------	--	----------

60-14-066	Paint walls and ceiling in Loughheed Highway Underpass. CHARGE: Traffic Management 1982 <u>ADDITIONAL INFORMATION:</u> The walls and ceiling of the underpass are covered in graffiti and are required to be painted. The Engineering Department has received several complaints from developers and others in the area concerning this matter. Funds are provided in the Traffic Management section of the Capital Budget.	\$ 3,500
-----------	---	----------


 DIRECTOR ENGINEERING

\$ 7,550
101

/ch