

ITEM 6
MANAGER'S REPORT NO. 75
COUNCIL MEETING 84/11/26

RE: EAST COLUMBIA STREET (NORTH ROAD) AND HOLMES STREET

MUNICIPAL MANAGER'S RECOMMENDATION:

1. THAT the recommendation of the Director Engineering be adopted.

* * * * *

TO: MUNICIPAL MANAGER 1984 11 15
FROM: DIRECTOR ENGINEERING
SUBJECT: EAST COLUMBIA STREET (NORTH ROAD) AND HOLMES STREET

RECOMMENDATION:

1. THAT this report be received by Council for information purposes.

REPORT:

At the 83 09 06 Council Meeting an enquiry was made as to the status, if any, for a traffic signal to be installed at this intersection. Upon instruction, we advised directly the Alderman who asked the question that while no signal then existed, it was being considered by the City.

Primarily in response to public concerns and in keeping with future plans to widen and upgrade East Columbia Street, New Westminster Council recently authorized the installation of this signal. With a full signal at Holmes Street and East Columbia Street, there will likely be some increase in traffic volumes on both Tenth Avenue and on Holmes Street. We will be updating our traffic volume statistics for both these streets and monitoring the effects of the new signal after it becomes operational, which will probably take place within the next month or so.

DE:cf

cc: () Traffic Supervisor
() Director Planning & Building Inspection

Attach.


DIRECTOR ENGINEERING