

ITEM 3
MANAGER'S REPORT NO. 62
COUNCIL MEETING 84/10/09

RE: LETTER FROM A & E WIRICK, 901 - 4353 HALIFAX STREET, BURNABY, B.C. V5C 5Z4
SIDEWALK COMPLAINT - HALIFAX STREET - 4300 BLK EAST END - 4400 BLK WEST END

MUNICIPAL MANAGER'S RECOMMENDATION:

1. THAT the recommendation of the Director Engineering be adopted.

* * * * *

TO: MUNICIPAL MANAGER 84 10 03
FROM: DIRECTOR ENGINEERING
SUBJECT: HALIFAX STREET - 4300 BLOCK EAST END
- 4400 BLOCK WEST END

RECOMMENDATION:

1. THAT A & E Wirick, of 901 - 4353 Halifax Street, Burnaby B.C., V5C 5Z4, receive a copy of this report.

REPORT:

On the Council Agenda for the regular Council meeting of 1984 September 17 was a letter from Arthur and Ellen Wirick complaining of the lack of sidewalk in a portion of the 4300 and 4400 Blocks of Halifax, of existing pavement being torn up and lack of parking control.

The length of the portion of the mentioned blocks which do not contain a concrete walk is an 84 metre section of the 4400 Block. This section is a development site owned by Dominion Construction. The development of the site is presently being actively pursued. The Engineering Department has on deposit bonding to cover the off-site services including a sidewalk. The developer, in the interim, has at their own expense constructed a chip walk across the site on Halifax connecting the existing concrete walks.

The asphalt on the street over the years had deteriorated to the point where it was advisable to grind the pavement and do an overlay. This has now been completed.

In the matter of traffic control, the Engineering Department's Traffic Division is reviewing this complaint along with others from the street and will attempt to solve the problem.

Mr. Wirick has been contacted and apprised of the contents of this report and the action the Engineering Department is taking.


DIRECTOR ENGINEERING

VMT:sp

Sketch Attached

