

ITEM	6
MANAGER'S REPORT NO.	11
COUNCIL MEETING	1981 02 09

Re: LETTER FROM MR. ROBERT A. FLEMING WHICH APPEARED ON THE AGENDA
FOR THE 1981 FEBRUARY 02 MEETING OF COUNCIL (Item 3h)
TRAFFIC CONDITION AT BOUNDARY ROAD AND RUMBLE STREET

The following report from the Municipal Engineer is in response to a letter from Mr. Robert A. Fleming which appeared on last week's agenda.

A traffic signal normally becomes operational within 3 to 4 months from the time that approval is obtained for its installation.

RECOMMENDATION:

1. THAT the recommendation of the Municipal Engineer be adopted.

* * * * *

TO: MUNICIPAL MANAGER

81 01 29

FROM: MUNICIPAL ENGINEER

SUBJECT: BOUNDARY ROAD AND RUMBLE STREET


RECOMMENDATION:

1. THAT the above report be sent to Mr. Robert A. Fleming of 3726 Irmin Street, Burnaby, B.C., V5J 1X2.

REPORT

Reference the submission from Mr. Robert A. Fleming of 3726 Irmin Street.

The captioned intersection is the junction of an arterial (Boundary Road) with a major collector (Rumble Street) and should in our opinion be signalized. We have therefore written to the City of Vancouver who have the responsibility for the design and construction of Boundary Road recommending the installation of a traffic signal.


MUNICIPAL ENGINEER

HB/ch

c.c. () Traffic Supervisor